
Magnetic Lock

wiring diagram











CUT OFF OUTPUT CONNECTOR AND STRIP WIRES.

POSITIVE CABLE IS MARKED WITH GREY STRIPES



SUPPRESSION UNIT AND ISN'T COVERED IN WARRANTY.